



# Corner Cupboard Materials



## Crown Molding



- Cut 2 pieces 1 1/2" wide
- Cut one 45° angle in the same direction on both ends
- Cut the other in the opposite direction

